




$P_i = 39,2 \text{ kW}$
 $K_j = 0,4$
 $P_o = 15,68 \text{ kW}$
 $P_o \sim 16 \text{ kW}$